

Work Order ID 74609

Monday, October 03, 2011 4:03:37 PM



Page 1

Item ID: D3161-7

Accept



Setup Start



Revision ID:

Stop



Item Name: Hinge 14.0"

Start Date: 10/3/2011 Start Qty: 8.00



Cust Item ID:

Required Date: 10/5/2011 Req'd Qty: 8.00



Customer:

Reference:

Approvals:

Process Plan:

Date: 11-10-11

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

D3161

Rev A2

100

0.00



Small Fab

Small Fab

Memo

0.00

Small Fab

(1) 72" Hinge makes (5) D3161-7 parts at 14" long Cut to length as per Dwg D3161

8/10/05 (8)

110

0.00



QC5- Inspect part completeness to step on W/O

QC

Memo

0.00

Quality Control

8/10/05

(x8)

120

0.00



Identify as per dwg & Stock Location ST 37

Packaging

Memo

0.00

Packaging

(8)

8/11-10-11

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 74609

Monday, October 03, 2011 4:03:37 PM



Page 2

Item ID:	D3161-7	Accept		Setup	Start	
Revision ID:					Stop	
Item Name:	Hinge 14.0"					
Start Date:	10/3/2011	Start Qty: 8.00				
Required Date:	10/5/2011	Req'd Qty: 8.00				
Reference:						

Approvals:	Process Plan:	Date:	Tooling:	Date:	Run	Start	
	QC:	Date:	SPC (Y/N):	Date:		Stop	

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130	QC21- Final Inspection - Work Order Release	0.00							
QC	Memo	0.00							
Quality Control									

R11-10-11
(5)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Monday, October 03, 2011 4:03:41 PM

Page 1

Work Order ID: 74609

Parent Item: D3161-7

Parent Item Name: Hinge 14.0"



Start Date: 10/3/2011

Required Date: 10/5/2011

Start Qty: 8.00

Required Qty: 8.00

Comments: IPP ☐ A ☐ 04.08.24 ☐ New Issue ☐ KJ/JLM ☐

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

MS20257-3-7200

Purchased

No

100

f

40.3759

1.2

9.6



Piano Hinge



Location

Loc Qty

Loc Code

ST449

0.00778948

116817

0.00778948

ST489A

40.36811

117543

2.126

118686

38.24211

Handwritten signature and date 10/5/11

9.6

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries




DESIGN <i>[initials]</i>	DRAWN BY <i>[initials]</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>[initials]</i>	APPROVED <i>[initials]</i>	DRAWING NO. D3161	REV. A SHEET 1 OF 1
DATE 02.04.24		TITLE HINGE	SCALE NTS
A	02.04.24	NEW ISSUE	
A1	04.02.27	ADDED D3161-5	
A2	04.06.30	ADD D3161-7 & D3161-9	

RELEASED
02.04.24 *[initials]*

P/N	LENGTH 'L'	DESCRIPTION
D3161-1	13.5"	HINGE (REPLACES MS20257-3-13.5 ON D2183)
D3161-3	15.0"	HINGE (REPLACES MS20257-3-15.0 ON D2950-041)
D3161-5	9.9"	HINGE
D3161-7	14.0"	HINGE
D3161-9	17.0"	HINGE

74609
P11-10-4



NOTES:

- ① MAKE FROM MS20257-3-7200 HINGE

Copyright © 2002 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries